

## DISCONTINUING ALL GEN II LIQUID LEVEL CONTROLLERS WITH FLANGED AND HAMMER UNION CONNECTIONS

This product notice is to inform you that we have discontinued all Gen II codes with flanged and hammer union connections.

New base codes for Gen 3 flanged and hammer union connections are listed below:

<b>Flanged</b>	<b>Gen 3 Code</b>
2" 150RF LH	LCA
2" 150RF RH	LCJ
2" 600RF LH	LCC
2" 600RF RH	LCM
3" 300RF LH	LCV
3" 600RF LH	LCW
3" 600RF RH	LDF
4" 150RF LH	LDM
4" 150RF RH	LDV
4" 300RF LH	LDN
4" 300RF RH	LDW

<b>Hammer Union</b>	<b>Gen 3 Code</b>
3" HU LH	LDC
3" HU RH	LDL
5" HU LH	LEM
5" HU RH	LEV

